
Section 22 Connecticut

Appendix B

Connecticut Coastal Structures Inventory Study

September 1988



**US Army Corps
of Engineers**
New England Division

SECTION 22
CONNECTICUT COASTAL STRUCTURES INVENTORY STUDY

PHASE I - NEW LONDON COUNTY

APPENDIX B
MYSTIC QUADRANGLE
RECORDS OF STRUCTURES WITH PHOTOGRAPHS

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

SEPTEMBER 1988

INVENTORY NUMBER: 1.10

QUAD : MYSTIC
ADDRESS: EAST GRAND STREET
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS AND PROTECTS ROAD RUNNING OUT TO EDWARDS P
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L= 300 FT, W= 2 FT, HIEGHT ABOVE MHW= 3 TO 4 FT

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1130

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL #11A NEG 5 SEAWALL LOOKING TOWARDS EDWARDS POINT
#2
#3
#4
#5

COMMENTS

SEAWALL CONTINUES FROM ROAD APROX. 100 FT ALONG RESIDENTIAL
PRPOERTY

INVENTORY NUMBER: 1.20

QUAD : MYSTIC
ADDRESS: EDWARDS POINT
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN&PIER CONDITION: GOOD
MAIN FUNCTION : SHORELINE EROSION PROTECTION
MATERIAL : STONE&CONCRETE

DESCRIPTION

GROIN THAT ALSO ACTS AS PIER WITH MOORING FOR SMALL BOATS

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1150

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11A NEG 3
#2 ROLL 11A NEG 4
#3 ROLL 11A NEG 5
#4 ROLL 11A NEG 6
#5


COMMENTS

ACCORDING TO RESIDENT WALL AND GROIN BUILT AFTER HURRICANES
ERODED SHORE FRONT PROPERTY

NY 1.20 #1



NY 1.20 #2



NY 1.20 #4



NY 1.20 #3



INVENTORY NUMBER: 1.30

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PROTECTION AND RETAINS/SUPPORTS LAND IN FRONT OF R
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L=1000 FT, W= ?, HEIGHT ABOVE EST MHW 10 FT

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11A NEG 7 SEAWALL WITH ROAD TO EDWARDS POINT ON RIGHT
#2 ROLL 11A NEG 8 SEAWALL FROM SOUTH LOOKING NORTH
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 1.40

QUAD : MYSTIC
ADDRESS: WALL ST
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN
MAIN FUNCTION : EROSION PROTECTION OF SHORE (?)
MATERIAL : STONE

CONDITION: GOOD

DESCRIPTION

APROX. L= 150 TO 180 FT, W= 15 TO 20 FT,
EST HEIGHT ABOVE MHW= 1 TO 2 FT

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1250

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11A NEG 9
#2 ROLL 11A NEG 10
#3
#4
#5

COMMENTS

GROIN EXTENDS OUT FROM EXPOSED BEDROCK SHORELINE AREA

NY 100-42



NY 100-42



INVENTORY NUMBER: 1.50

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS&PIERS CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF RESIDENCE AND SUPPORT/RETENTION OF L
MATERIAL : STONE

DESCRIPTION

DIMENSIONS OF SEAWALLS AND PIERS VARIABLE

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1325

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 1 NEG 14 SEEWALL LOOKING NORTH
#2 ROLL 1 NEG 15 SEAWALL LOOKING NORTH
#3 ROLL 1 NEG 16 SEAWALL LOOKING NORTH
#4 ROLL 1 NEG 17 SEAWALL LOOKING NORTH
#5

COMMENTS

AREA OF DENSLEY PAKHED HOMES BUILT CLOSE TO WATER. NO SANDY
BEACH AREAS; BUT RESIDENTS CLAIM HEAVY SILTATION FROM RIVER

MY 1.30 #1

MY 1.30 #2



MY 1.30 #1

MY 1.30 #2



INVENTORY NUMBER: 2.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION:
MAIN FUNCTION : PROVIDES INTERCEPTION OF WAVES FOR STONINGTON HARB
MATERIAL : STONE

DESCRIPTION

APROX. L= 2400 FT, EST HEIGHT ABOVE MHW= 6 FT

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1420

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : OPEN WATER
LAND USE :

- PHOTOS -

#1 NONE
#2
#3
#4
#5

COMMENTS

STUCTURE BUILT BY CORPS OF ENGINEERS; ONE OF TWO BREAKWATERS
PROTECTING HARBOR

NO PHOTOGRAPHS

INVENTORY NUMBER: 3.00

QUAD : MYSTIC
ADDRESS: STONNINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION:
MAIN FUNCTION : PROVIDES INTERCEPTION OF WAVES FOR STONINGTON HARB
MATERIAL : STONE

DESCRIPTION

APROX. L= 1840 FT, EST HEIGHT ABOVE MHW= 7 FT

INSPECTION DATE : 06/08/87 INSPECTION TIME: 1440

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : OPEN WATER
LAND USE :

- PHOTOS -

#1 ROLL 1 NEG 20 BREAKWATER WITH SMALL GROIN IN FOREGROUND
#2 ROLL 1 NEG 26 BREAKWATER LOOKING WEST
#3 ROLL 2 NEG 15 AND NEG 16 BREAKWATER FROM WAMPHASSUC PT,
#4 LOOKING SOUTH EAST
#5

COMMENTS

ONE OF TWO BREAKWATERS PROTECTING STONINGTON HARBOR
STRUCTURE BUILT BY CORPS OF ENGINEERS.

NY 3.00 #1



NY 3.00 #2



NY 3.00 #1



INVENTORY NUMBER: 4.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : PROTECTS BEACH FROM EROSION
MATERIAL : ROCK

DESCRIPTION

APROX. L=150 FT, W= 20 FT

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1420

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 1 NEG 18 GROIN FROM SOUTH
#2 ROLL 2 NEG 19 GROIN FROM NORTH
#3
#4
#5

COMMENTS

NO SEDIMENT TRAPPED ON SOUTH SIDE, BEACH (DU BOIS) FOR
STONINGTON RESIDENTS ON NORTH SIDE

3. 4. 00 #1



3. 4. 00 #2



INVENTORY NUMBER: 5.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND IN FRONT OF HOME
MATERIAL : STONE

DESCRIPTION

APROX. L= 120 FT, HEIGHT ABOVE MHW= 10 FT

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1450

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 1 NEG 21 BULKHEAD WIH NEIGHBORING GROIN
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 6.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR.
MAIN FUNCTION : PROTECTS PRIVATE BEACH FROM EROSION
MATERIAL : ROCK

DESCRIPTION

APROX. L= 105 FT, W= 45 FT, HEIGHT ABOVE MHW= 1 FT

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1450

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 1 NEG 22 GROIN FROM NORTH
#2
#3
#4
#5

COMMENTS

NO SAND ACCUMULATED ON NORTH SIDE OF GROIN

MY 6.20 #1



INVENTORY NUMBER: 7.00

QUAD : MYSTIC
ADDRESS: WATER STREET, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : PROTECTS RESIDENTIAL LOTS FROM EROSION, RETAINS LA
MATERIAL : STONE

DESCRIPTION

SEAWALL EXTENDS FROM 12 WATER STREET TO MONSANTO PROPERTY
APROX L= 1000FT

INSPECTION DATE : 06/18/87 INSPECTION TIME: 1450

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 1 NEG 27 SEAWALL FROM STRUCTURE 8
#2 ROLL 2 NEG 2 DAMAGED PORTION OF SEAWALL
#3 ROLL 2 NEG 5 DAMAGED PORTION OF SEAWALL
#4
#5

COMMENTS

SEAWALL HAS RUBBLE APRON, PORTION OF SEAWALL DAMAGED

NY 7.03 #1



NY 7.03 #2



NY 7.03 #3



INVENTORY NUMBER: 8.00

QUAD : MYSTIC
ADDRESS: WATER ST., STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: JETTY & LIGHT CONDITION: FAIR
MAIN FUNCTION : PROTECTS MOORING AREA TO NORTH, LIGHT IS CHANNEL M
MATERIAL : STONE

DESCRIPTION

APROX. L= 900 FT, W=50 FT

INSPECTION DATE : 06/19/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : INDUSTRIAL (MONSANTO)


- PHOTOS -

#1 ROLL 2 NEG 6 JETTY FROM SOUTH
#2 ROLL 2 NEG 8 EXPOSED AREA IMMEDIATELY NORTH OF JETTY
#3 ROLL 1 NEG 24 JETTY AND LIGHT FROM WATER LOOKIN NORTH
#4
#5

COMMENTS

STONES WERE ORIGINALLY SQUARE TO FIT TOGETHER EVENLY BUT
HAVE BEEN REARRANGED BY WAVE ACTION

MY 2.00 #1



MY 2.00 #2



MY 2.00 #3



INVENTORY NUMBER: 9.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS PARKING LOT, PROTECTS PROPERTY FROM EROSIO
MATERIAL : WOOD/STONE

DESCRIPTION

NORTH HALF IS WOOD, SOUTH HALF IS STONE
APROX. L= 450 FT, HEIGHT ABOVE MHW= 3 FT

INSPECTION DATE : 06/19/87 INSPECTION TIME: 1245

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 2 NEG 7 SEAWALL FROM END OF JETTY
#2 ROLL 2 NEG 9 WOODEN HALF OF SEAWALL
#3
#4
#5

COMMENTS

MC 3.00 #1



MC 3.00 #2



INVENTORY NUMBER: 10.00

QUAD : MYSTIC
ADDRESS: WATER ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : FOUNDATION FOR PIER AND RESTAURANT, EROSION CONTROL
MATERIAL : STONE

DESCRIPTION

APROX. L= 105 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 06/19/87 INSPECTION TIME: 1300

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SKIPPER'S DOCK RESTAURANT
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 2 NEG 10 PIER BULKHEAD AND RESTAURANT FROM SOUTH
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 11.00

QUAD : MYSTIC
ADDRESS: WATER ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND AND EROSION PROTECTION
MATERIAL : STONE&CONCRETE

DESCRIPTION

SERIES OF SEAWALLS
APROX. HEIGHT ABOVE MHW 5 FT

INSPECTION DATE : 06/19/87 INSPECTION TIME: 1305

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 2 NEG 11,12,13,14 SERIES OF SMALL SEAWALLS
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 11.10

QUAD : MYSTIC
ADDRESS: WATER ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS CONDITION: FAIR
MAIN FUNCTION : EROSION PROTECTION AND RETAINS LAND
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L=750 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1050

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL

- PHOTOS -


#1 ROLL 3 NEG 1 WALL FROM SKIPPER DOCK TO TOWN PARKING AREA
#2 ROLL 3 NEG 2 WALL INFRONT OF TOWN PARKING AREA AND GAZEBO
#3
#4
#5

COMMENTS

0000000000



0000000000



INVENTORY NUMBER: 12.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: FAIR
MAIN FUNCTION : PROTECTS AGAINST EROSION AND RETAINS LAND
MATERIAL : STONE

DESCRIPTION

APROX. L= 55 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1055

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 3 NEG 4 REVETMENT FROM A PIER
#2
#3
#4
#5

COMMENTS

PIER EXTENDS FROM NORTH END OF REVETMENT, 2 DOLPHINS AT
NORTH END OF REVETMENT FOR MOORING PURPOSES



INVENTORY NUMBER: 13.00

QUAD : MYSTIC
ADDRESS: NORTH WEST ST, STON.VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: WAVE ATTENUATOR CONDITION: GOOD
MAIN FUNCTION : INTERCEPTION OF WAVES TO PROTECT MOORING AREA
MATERIAL : WOOD

DESCRIPTION

TIMBER TIE PILES AND FIXED WOOD WAVE ATTENUATOR
APROX. L=400 FT, W= 3 FT, HEIGHT ABOVE MHW= 2.3 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1100

- LAND CLASSIFICATION -

PERMIT NUMBER: 86102
OWNER'S NAME : HARBOR EDGE ASSOC.
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 3 NEG 5 WAVE ATTENUATOR
#2
#3
#4
#5

COMMENTS

NY 100-100000



INVENTORY NUMBER: 14.00

QUAD : MYSTIC
ADDRESS: NORTH WEST ST, STON.VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND, PREVENTS EROSION
MATERIAL : STONE

DESCRIPTION

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1100

- LAND CLASSIFICATION -

PERMIT NUMBER: 830198
OWNER'S NAME : HARBOR EDGE ASSOCIATES
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -



#1 ROLL 3 NEG 6,7,8 SOUTHSIDE OF BULKHEAD AND DOCKING FACILITY
#2 ROLL 3 NEG 9 EAST SIDE OF STRUCTURE FROM DOCK
#3
#4
#5

COMMENTS

NY 14.00 #1



NY 14.00 #2



INVENTORY NUMBER: 15.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD
MAIN FUNCTION : RETAINS LAND
MATERIAL : STONE&CONCRETE

CONDITION: FAIR

DESCRIPTION

APROX. L=900 FT, W=75 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1117

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : COMMERCIAL


- PHOTOS -

#1 ROLL 3 NEG 10,11,12,13 STRUCTURE FROM SOUTH
#2
#3
#4
#5

COMMENTS

AREA IMMEDIATELY SOUTH OF STRUCTURE IS AN EXPOSED SANDY
SLOPE USED AS BOAT RAMP TO ALLOW ACCESS TO WATER

MY 16.03 #1



INVENTORY NUMBER: 16.00

QUAD : MYSTIC
ADDRESS: ELM ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: FAIR
MAIN FUNCTION : PROTECTION OF POINT FROM EROSION
MATERIAL : STONE

DESCRIPTION

APROX. L=225 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1150

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : TOWN OF STONINGTON
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 3 NEG 14 FROM DOCK LOOKING WEST TO POINT OF STRUCTURE
#2
#3
#4
#5

COMMENTS

FISHERMAN'S PIER LEASED FROM TOWN



INVENTORY NUMBER: 17.00

QUAD : MYSTIC
ADDRESS: FRONT ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS CONDITION:
MAIN FUNCTION : PROTECTION FROM WAVE ACTION, RETAINS LAND
MATERIAL : STONE

DESCRIPTION

SERIES OF SEAWALLS, APROX. L= 1500 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 855087
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 3 NEG 15,16,17 SEAWALLS LOOKING NORTH
#2 ROLL 3 NEG 18 NORTH END OF SEAWALL LOOKING SOUTH FROM PIER
#3
#4
#5

COMMENTS

NY 17.00 41



INVENTORY NUMBER: 18.00

QUAD : MYSTIC
ADDRESS: STONINGTON VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: FAIR
MAIN FUNCTION : RETAINS LAND AND PREVENTS EROSION
MATERIAL : STEEL

DESCRIPTION

APROX. L=36 FT, HEIGHT ABOVE MHW= 3 TO 4 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1225


- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : MR. POPIEL
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 3 NEG 19 STRUCTURE FROM SOUTH END LOOKING NORTH
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 19.00

QUAD : MYSTIC
ADDRESS: 194 WATER ST, STON. VILL.
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PROTECTS EROSION OF LAND AND RETAINS LAND
MATERIAL : STONE

DESCRIPTION

APROX. L= 750 FT,

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1215

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : DODSON BOATYARD
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 3 NEG 20 SEAWALL AT BOAT YARD
#2 ROLL 3 NEG 21 SEAWALL LOOKING NORTH FROM BOATYARD TO
#3 WADAWANUCK CLUB
#4
#5

COMMENTS

SEAWALL EXTENDS FROM STEEL BULKHEAD (STRUCTURE 18) TO
WADAWANUCK CLUB, MOORING AND DOCKING FACILITIES

000000 41



000000 42



INVENTORY NUMBER: 20.00

QUAD : MYSTIC
ADDRESS: MATHEWS ST., STON.VILLAGE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION AND RETAINS LAND
MATERIAL : STONE

DESCRIPTION

APPROX. L= 235 FT, W= 3 FT, HEIGHT ABOVE MHW= 3 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1255

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : WADAWANUCK CLUB
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 3 NEG 22 SEAWALL LOOKING SOUTH FROM CLUB PROPERTY
#2 ROLL 3 NEG 23 SEAWALL LOOKING NORTH FROM PRIVATE BEACH
#3 ROLL 3 NEG 24 SEAWALL LOOKING NORTH FROM PRIVATE BEACH
#4
#5

COMMENTS

MY 23.00 31



MY 23.00 32

MY 23.00 37



INVENTORY NUMBER: 21.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RR REVETMENT
MAIN FUNCTION : PROTECTS SLOPE
MATERIAL : STONE

CONDITION: GOOD

DESCRIPTION

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1300

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : CONRAIL
ACCESS : PRIVATE
LAND USE : INDUSTRIAL

- PHOTOS -

#1 ROLL 3 NEG 25 RR REVETMENT LOOKING N. FROM WADAWANUCK CLUB
#2
#3
#4
#5

COMMENTS

MY 21.10 #1



INVENTORY NUMBER: 22.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : RETARDS EROSION OF BEACH TO S. OF GROIN; SECURES
MATERIAL : STONE

DESCRIPTION

APPROX. L= 66 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1312

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 3 NEG 26 W.SHORE OF PAWCATUCK PT LOOKING S. FROM RR TRK
#2 ROLL 4 NEG 1 GROIN FROM NORTH
#3 ROLL 4 NEG 2 GROIN FROM SOUTH
#4
#5

COMMENTS

NY 22.00 #1



NY 22.00 #2



NY 22.00 #3



INVENTORY NUMBER: 23.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : RETAINS SAND AT BEACH AREA
MATERIAL : STONE

DESCRIPTION

APPROX. L= 75 FT, W= 12 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1325

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 3 GROIN FROM EAST
#2
#3
#4
#5

COMMENTS

ME 13.00 #1



INVENTORY NUMBER: 24.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIP RAP SH LINE CONDITION:
MAIN FUNCTION : PROTECTS SHORELINE
MATERIAL :

DESCRIPTION

APPROX. L= 750 FT.

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1340

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 4-5 PANARAMIC VIEW OF CRESCENT SHAPED SHORELINE
#2 LINED W/ DEPOSITED STONE LOOKING SOUTH/S.W.
#3 NEG 6 SHORELINE AREA SOUTH OF STRUCTURE 24
#4
#5

COMMENTS

NY 24.10 41



NY 24.10 41



INVENTORY NUMBER: 25.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN FIELD CONDITION: POOR
MAIN FUNCTION : ACCUMULATES AND RETAINS SANDY BEACH IN A TYPICAL R
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 20-30 FT, W= 4-5 FT, HEIGHT ABOVE MWH= 1-2 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 4 NEG 7 30' ROCK GROIN W/OTHERS VISIBLE BEHIND IT-POOR
#2 NEG 8 FROM 4TH GROIN LOOKING NORTH
#3
#4
#5

COMMENTS

THE GROIN FIELD IS A SYSTEM OF 4 ROCK GROINS IN POOR CONDI-
TION HOWEVER SOME SAND HAS ACCRETED
LOCATED APPROX. 80 YDS S. OF STRUCTURE PREVIOUSLY NOTED

MY 25.00 #1



MY 25.00 #2



INVENTORY NUMBER: 26.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : MAINTAINS BEACH AND SUPPORTS DOCK CONSTRUCTION
MATERIAL : CEMENT

DESCRIPTION

APPROX. L= 80 FT, W= 8 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 9 SHOWS STRUCTURE #26
#2
#3
#4
#5

COMMENTS

SOUTH SIDE OF STRUCTURE IS GRASSY MARSH AREA. STRUCTURE IS
LOCATED 60-70 YDS S. OF LAST GROIN IN #25 GROIN FIELD.

MY 26.22 41



INVENTORY NUMBER: 27.00

QUAD : MYSTIC
ADDRESS: WAMPHASSUC PT RD
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: 3 GROINS CONDITION: POOR
MAIN FUNCTION : RETAINS, ACCRETES SANDY BEACH IN PLACE OF GRASSY M
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 50-65 FT, W= 4-6 FT, HEIGHT ABOVE MHW= 1-3 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1530

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 10 FIRST 2 OF 3 GROINS AND SAND IN BETWEEN
#2 NEG 11 SECOND IN GROIN SERIES LOOKING TO NORTH
#3
#4
#5

COMMENTS

MR 27.00 #1



MR 27.00 #2



INVENTORY NUMBER: 28.10

QUAD : MYSTIC
ADDRESS: SKIPPER AVE
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION:
MAIN FUNCTION : PROTECTS RESIDENTIAL LOTS FROM WAVE ACTION DURING
MATERIAL : CONCRETE

DESCRIPTION

APPROX. L= 1000 FT

INSPECTION DATE : 06/19/87 INSPECTION TIME: 1430

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS :
LAND USE :

- PHOTOS -

#1 ROLL 2 NEG 18 LOOKING E. ALONG SEAWALL TOWARDS WAMPHASSUC PT
#2 NEG 19 WEST SHORE OF LORD'S POINT LOOKING NORTH
#3
#4
#5

COMMENTS

SHORE IS COMPOSED OF EXPOSED BEDROCK

NY 21.10 #1



NY 21.10 #2



INVENTORY NUMBER: 28.20

QUAD : MYSTIC
ADDRESS: BEACH AVENUE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION:
MAIN FUNCTION : PROTECTS ACCESS ROAD FROM EROSION
MATERIAL : STONE

DESCRIPTION

APPROX. 220 FT, W= 12 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1020

- LAND CLASSIFICATION -

PERMIT NUMBER: 84063
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 16 REVETMENT LOOKING NORTHWEST FROM BOULDER AVE
#2
#3
#4
#5

COMMENTS

MY 23.20 #1



INVENTORY NUMBER: 29.00

QUAD : MYSTIC
ADDRESS: NOTES AVE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PROTECTS ROAD FROM WAVE ACTION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APPROX. L= 33 FT, W= 2 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1020

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PUBLIC
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 17 SEAWALL LOOKING SOUTH WEST FROM REVETMENT-#28
#2
#3
#4
#5

COMMENTS

MY 29.00 #1



INVENTORY NUMBER: 30.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS (5) CONDITION: GOOD
MAIN FUNCTION : PROTECTS RESIDENTIAL LOTS FROM WAVE ACTION; RETAIN
MATERIAL : CONCRETE/ST.CEM

DESCRIPTION

APPROX. 300 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1105

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 21 FIRST 2 SEAWALLS LOOKING NORTH FORM PIER
#2 NEG 22-23 3 SEAWALLS LOOKING S. FROM SAME PIER ABOVE
#3
#4
#5

COMMENTS

MY 10.00 #1



MY 10.10 #1



INVENTORY NUMBER: 31.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD

MAIN FUNCTION : MAINTAINS/RETAINS PRIVATE LOT

MATERIAL : CONCRETE

DESCRIPTION

APPROX. W= 1 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1050

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 18 CONCRETE AND STONE SEAWALLS

#2

#3

#4

#5

COMMENTS

NY 11.00 #1



INVENTORY NUMBER: 32.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS/MAINTAINS PRIVATE LOT
MATERIAL : STONE IN CONCRE

DESCRIPTION

APPROX. W= 1 FT, HEIGHT ABOVE MHW=5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1100

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 19-20 SEAWALL AND SMALL PRIVATE BEACH
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 33.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS-SERIES CONDITION: FAIR
MAIN FUNCTION : MAINTAINS/RETAINS PRIVATE LOTS
MATERIAL : STONE IN CONCRE

DESCRIPTION

APPROX. HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1132

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 4 SEAWALLS LOOKING SOUTH FROM STRUCTURE 35
#2
#3
#4
#5

COMMENTS

NY 73.00 #1



INVENTORY NUMBER: 34.00

QUAD : MYSTIC
ADDRESS: JAMES ST
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : MAINTAINS LORD'S PT ASSOC. PROPERTY TO PREVENT FLD
MATERIAL : STONE&CONCRETE

DESCRIPTION

APPROX. L=91 FT, W= 2 FT, HEIGHT ABOVE MHW= 3 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1130

- LAND CLASSIFICATION -

PERMIT NUMBER: 780404
OWNER'S NAME : LORD'S PT ASSOCIATION
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 5 NEG 3 SEAWALL LOOKING N. FROM ADJOINING PROPERTY TO S
#2
#3
#4
#5

COMMENTS

NY 34.10 #1



INVENTORY NUMBER: 35.00

QUAD : MYSTIC
ADDRESS: LINDBERG AVE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS-SERIES CONDITION: FAIR
MAIN FUNCTION : PROTECTS 9 PRIVATE HOMES; RETAINS LAND AND EROSION
MATERIAL :

DESCRIPTION

APPROX. L= 300 FT, W= 2 FT, HEIGHT ABOVE MHW= 6 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1115

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 4 NEG 24-26 PANORAMIC VIEW OF SEAWALLS
#2
#3
#4
#5

COMMENTS

MY 15.00 #1



INVENTORY NUMBER: 36.00

QUAD : MYSTIC
ADDRESS: QUIANBOG COVE
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : RR BRIDGE/PROTECTS SLOPE
MATERIAL :

DESCRIPTION

APPROX. L= 300 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1120


- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : AMTRAK/CONRAIL?
ACCESS :
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 4 NEG 27 BRIDGE LOOKING WEST
#2 ROLL 5 NEG 1-2 PANORAMIC VIEW OF BRIDGE LOOKING WEST
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 37.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: WALL/GROIN/DOCK CONDITION: GOOD
MAIN FUNCTION : RETAINS SAND ON SMALL BEACH AND MAINTAINS BACKYARD
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 150 FT, W= 20 FT, HEIGHT ABOVE MHW= 6FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE PROP/PUBLIC BEACH
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 5-6 PANORAMA OF SM. BEACH W/BOULDERS, WALL &
#2 GROIN/DOCK LOOKING FROM SOUTH BEACH
#3 NEG 7 ROCK GROIN LOOKING N. FROM ADJOINING PROP. TO S
#4
#5

COMMENTS

BOULDERS APPEAR TO BE NATURALLY DEPOSITED. NEIGHBORS OBJECT
TO PRESENCE OF WALL BEC/IT RUINS NORMAL TIDAL ACTION & OBSTR
UCTS VIEW. ANDERSON DOCK ADJACENT TO SM., PRIVATE BEACH...

NY 27.12 41



NY 27.12 42



INVENTORY NUMBER: 38.00

QUAD : MYSTIC
ADDRESS: 8 E. SHORE RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS PROPERTY
MATERIAL : STONE IN CEMENT

DESCRIPTION

APPROX. L= 210 FT, W= 3 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : M/M SANTA MARIA
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 8 SEAWALL FROM NORTH LOOKING SOUTH
#2 NEG 9 SEAWALL FROM ADJOINING PROPERTY TO S. LOOKING N
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 39.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : RETAINS PROPERTY; HURRICANE PROTECTION EROSION CON
MATERIAL : STONE

DESCRIPTION

APPROX. L= 180FT, W= 2FT, HEIGHT ABOVE MHW= 6 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1210

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 10 REVETMENT FROM ADJOINING PROP. TO NE LOOKING W
#2 NEG 11 SEC. OF REVETMENT DAMAGED BY HURRICANE
#3
#4
#5

COMMENTS

SOME BACKSIDE SCOUR; 1978, PLAN AVAILABLE FROM TOWN OF STON-
INGTON - POWELL ENGINEER; PLAN SHOWING LAYOUT OF LOT; SEA-
WALL WITH SM. OPENING IN CENTER TO ALLOW ACCESS TO WATER.



INVENTORY NUMBER: 40.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL

CONDITION: GOOD

MAIN FUNCTION : RETAINS PROPERTY

MATERIAL : CONCRETE

DESCRIPTION

APPROX. L= 99 FT, W= 1.5 FT, HEIGHT ABOVE MHW=5 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 12-13 PANORAMA OF SEAWALL FROM WATER

#2

#3

#4

#5

COMMENTS



INVENTORY NUMBER: 41.10

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: 2 GROINS CONDITION: GOOD
MAIN FUNCTION : MAINTAINS SANDY BEACH AREA
MATERIAL : STONE

DESCRIPTION

APPROX. L= 180 FT, W= 20 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 5 NEG 14 FROM EAST LOOKING WEST TOWARDS POINT
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 41.20

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL

CONDITION:

MAIN FUNCTION :

MATERIAL : STONE IN CEMENT

DESCRIPTION

APPROX. L= 200 FT, W= 2 FT, HEIGHT ABOVE MHW= 2 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE :

- PHOTOS -

#1 NO PICTURE

#2

#3

#4

#5

COMMENTS

NO PHOTOGRAPHS

INVENTORY NUMBER: 42.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/PIER

CONDITION: FAIR

MAIN FUNCTION : RETAINS PROPERTY; PROTECTS PRIVATE PROPERTY FROM E

MATERIAL : STONE/WOODEN

DESCRIPTION

APPROX. L= 75 FT, W= 5 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1405

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE :

- PHOTOS -

#1 ROLL 5 NEG 15 BULKHEAD FROM SOUTH, LOOKING NORTH
#2 NEG 16 BULKHEAD FORM PIER ON SOUTH END OF BULKHEAD
#3
#4
#5

COMMENTS

MY 42.00 #1



MY 42.00 #2



INVENTORY NUMBER: 43.00

QUAD : MYSTIC
ADDRESS: COVE RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION:
MAIN FUNCTION : PREVENTS EROSION OF WESTSHORE OF LATIMER POINT
MATERIAL : ROCK

DESCRIPTION

INSPECTION DATE : 07/01/87 INSPECTION TIME: 1400

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 17 SOUTH LOOKING NORTH
#2
#3
#4
#5

COMMENTS

MY 43.00 #1



INVENTORY NUMBER: 44.00

QUAD : MYSTIC
ADDRESS: MASONS ISLAND RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PROTECTS PRIVATE LOT FROM EROSION
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 750 FT, HEIGHT ABOVE MHW= 3.5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1035

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 21-23 SEAWALL (PANORAMIC VIEW)
#2
#3
#4
#5

COMMENTS

AREA - MARSH WITH INTERMITTENT PATCHES OF SAND - NATURALLY
DEPOSITED LOOSE BOULDERS

MY 44.00 #1



B102

INVENTORY NUMBER: 45.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROINS (2) CONDITION: FAIR

MAIN FUNCTION : PROTECTS SMALL BEACH AREA

MATERIAL : ROCK

DESCRIPTION

NORTH GROIN-APPROX. L= 75 FT, W= 3 FT, HEIGHT ABOVE MHW=3 FT

SOUTH GROIN-APPROX. L= 60 FT, W= 3 FT, HEIGHT ABOVE MHW=3 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1035

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 5 NEG 25 SOUTH GROIN

#2

#3

#4

#5

COMMENTS

MARSH WITH INTERMITTENT PATCHES OF SAND AND LOOSE BOULDERS

MY 45.00 #1



INVENTORY NUMBER: 46.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROINS (SERIES) CONDITION: POOR
MAIN FUNCTION : RETAINS/PROTECTS SMALL PRIVATE BEACHES
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 21 FT, W= 3 FT, HEIGHT ABOVE MHW= 0 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1055

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 1 ROCK GROINS FROM NORTH LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

AREA - SALT MARSH WITH SANDY SHORE & LOOSE BOULDERS. SAND IN
LITTLE BAY DRIFTS CLOCKWISE.

MY 46.CC #1



INVENTORY NUMBER: 47.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD

MAIN FUNCTION : STABILIZES/PROTECTS SLOPE

MATERIAL : LOOSE BOULDERS

DESCRIPTION

APPROX. L= 75 FT, V= 1500 CUBIC FT OF ROCK, HEIGHT ABOVE
MHW= 6 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1100

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS --

#1 ROLL 6 NEG 2 REVETMENT FORM WATER'S EDGE
#2
#3
#4
#5

COMMENTS

SHORE ON SALT MARSH WITH SANDY SHORE, LOOSE BOULDERS

MY 47.00 #1



INVENTORY NUMBER: 48.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAINS PRIVATE LOT; REVENTS EROSION OF YARD BEHIN
MATERIAL : STONE IN CONCRE

DESCRIPTION

APPROX. L= 75 FT, W= 2 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1107

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 3 SEAWALL FORM WATER
#2
#3
#4
#5

COMMENTS

AREA - SALT MARSH WITH SANDY SHORELINE

MY 48.30 #1



INVENTORY NUMBER: 49.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD
MAIN FUNCTION : SUPPORTS DOCK; BASE FOR DOCK AND NORTHSIDE HAS SAND
MATERIAL : CONDITION: GOOD

DESCRIPTION

APPROX. L= 35 FT, W= 8 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1105

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 4 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SAND IN BY FLOATING CLOCKWISE
- SMALL BOULDERS AND RUBBLE SHORE
- LARGE BOULDERS DEPOSITED AT TOE OF SLOPE OF HOUSE LOTS

MY 49.00 #1



INVENTORY NUMBER: 50.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT

CONDITION: FAIR

MAIN FUNCTION : PROTECT SHORELINE

MATERIAL : STONE

DESCRIPTION

APPROX. L= 150 FT, HEIGHT ABOVE MHW= 3 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1135

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 5 REVETMENT AND ADJACENT PIER

#2

#3

#4

#5

COMMENTS

THE SHORE IS COMPOSED OF SALT MARSH W/INTERMITTENT SANDY
PATCHES

MY 50.00 #1



INVENTORY NUMBER: 51.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: FAIR
MAIN FUNCTION : PROTECTS SHORE AREA; TRAPS SAND
MATERIAL : STONE

DESCRIPTION

APPROX. L= 90 FT, W= 20 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1125

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 6 ^{Rock}~~LOCK~~ GROIN FROM DOCK ON NORTH (TO TRAP SAND)
#2
#3
#4
#5

COMMENTS

REACH - SALT MARSH AND BOULDERS AND COUBBLES
SOME SAND ACCRETION (?PLACEMENT) BETWEEN AREAS PROTECTED BY
GROINS AND DOCKS

MY 51.00 #1



INVENTORY NUMBER: 52.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD

MAIN FUNCTION : PROTECTS PROPERTY TO PREVENT EROSION

MATERIAL :

DESCRIPTION

APPROX. W= 2 FT, HEIGHT ABOVE MHW= 6 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1145

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 7 DOCK NEXT TO SEAWELL

#2 NEG 8 SUSPENSION DOCK NEXT TO STRUCTURE 52

#3

#4

#5


COMMENTS

LOST FIRST HOUSE DURING HURRICANE OF 1938
BEACH AREA, SAND, SALT MARSH GRASS, AND ROCKS

MY 52.00 #1



MY 52.00 #2



INVENTORY NUMBER: 53.00

QUAD : MYSTIC -
ADDRESS:
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIP RAP SHRLINE CONDITION: GOOD
MAIN FUNCTION : UNCLEAR-NO EROSION PROTECTION DUE TO NATURAL PROTE
MATERIAL :

DESCRIPTION

APPROX. HEIGHT MHW= 15 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1315

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 9-10 BOULDER REVETMENT IN FRONT OF GREY HOUSE AND
#2 SURROUNDING AREA
#3
#4
#5

COMMENTS

AREA - ROCKY SHORELINE; NO SAND, JUST BOULDERS

MY 53.00 #1



INVENTORY NUMBER: 54.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROINS (2)/DOCK CONDITION: GOOD
MAIN FUNCTION : AS RECREATIONAL DOCK (?) NO BEACH
MATERIAL : ROCK

DESCRIPTION

APPROX. L= 150 FT, HEIGHT ABOVE MHW= 10 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1310

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 6 NO PICTURE
#2
#3
#4
#5

COMMENTS

VERY ROCK SHORELINE - COBBLES AND BOULDERS

NO PHOTOGRAPHS

INVENTORY NUMBER: 55.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/RPRP/GR

CONDITION: GOOD

MAIN FUNCTION : PREVENTS EROSION

MATERIAL : LOOSE BOULDERS

DESCRIPTION

APPROX. L= 1000 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1315

- LAND CLASSIFICATION -

PERMIT NUMBER:

0

OWNER'S NAME :

MASON'S ISLAND YACHT CLUB

ACCESS :

PRIVATE

LAND USE :

RECREATIONAL

- PHOTOS -

- #1 ROLL 6 NEG 11 LOOKING SOUTH ALONG SEAWALL TO PIER
- #2 ENDERS ISLAND IN BACKGROUND
- #3
- #4
- #5

COMMENTS

SMALL BEACH AREA AT FRONT OF MASONS'S ISLAND YACHT CLUB,
REST OF SHORE VERY ROCKY - LARGE BOULDERS

MY 55.CO #1



INVENTORY NUMBER: 56.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : ACCESS TO WOODEN PIER/RETAINS SM. PRIV. BEACH IN F
MATERIAL : STONE IN CEMENT

DESCRIPTION

APPROX. L= 105 FT, W= 12 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1325

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : MASON'S ISLAND YACHT CLUB
ACCESS : PRIVATE
LAND USE : RECREATIONAL (?)

- PHOTOS -

#1 ROLL 6 NEG 12 GROIN FROM SOUTH LOOKING NORTH
#2
#3
#4
#5

COMMENTS

SEE #55

MY 56.00 #1



INVENTORY NUMBER: 57.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL

CONDITION: GOOD

MAIN FUNCTION : PROTECTS ROAD

MATERIAL : STONE IN CEMENT

DESCRIPTION

APPROX. W= 1 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1330

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME :

ACCESS : PRIVATE

LAND USE :

- PHOTOS -

#1 ROLL 6 NEG 13 SEAWALL

#2

#3

#4

#5

COMMENTS

SEAWALL ADJACENT TO BRIDGE TO ENDERS ISLAND

MY 57.00 #1



INVENTORY NUMBER: 58.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL
MAIN FUNCTION : PROTECTS ROAD
MATERIAL : STONE

CONDITION: GOOD

DESCRIPTION

APPROX. L= 400 FT HEIGHT ABOVE MHW= 10 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1340

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 6 NEG 14 E. SIDE OF CAUSEWAY FROM MASON ISLE LOOKING S.
#2
#3
#4
#5

COMMENTS

MY 53.00 #1



INVENTORY NUMBER: 59.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL

CONDITION: FAIR

MAIN FUNCTION : PREVENTS EROSION

MATERIAL : STONE

DESCRIPTION

APPROX. L= 210 FT, W= 1.5 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1340

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME : SOCIETY OF ST. EDMUND

ACCESS : PRIVATE

LAND USE :

- PHOTOS -

#1 NO PICTURE

#2

#3

#4

#5

COMMENTS

ADJOINS BRIDGE BETWEEN MASON ISLAND AND ENDERS ISLAND

NO PHOTOGRAPHS

INVENTORY NUMBER: 60.00

QUAD : MYSTIC
ADDRESS:
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: STONE REVETMENT CONDITION: GOOD
MAIN FUNCTION : PREVENTS EROSION
MATERIAL : STONE

DESCRIPTION

APROX. L= 800 FT, HEIGHT ABOVE MHW= 4 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1345

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SOCIETY OF ST. EDMUND
ACCESS : PRIVATE
LAND USE : INSTITUTIONAL

- PHOTOS -

#1 ROLL 6 NEG 15 REVETMENT FROM NORTH LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

AREA - ENDERS ISLAND COMPLETELY LINED WITH WALLS & BOULDER
REVETMENTS

MY 60.00 #1



INVENTORY NUMBER: 61.00

QUAD : MYSTIC

ADDRESS:

TOWN : STONINGTON

STATE : CT

COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL

CONDITION: GOOD

MAIN FUNCTION : TO PREVENT EROSION

MATERIAL : STONE

DESCRIPTION

APPROX. L= 1200 FT, HEIGHT ABOVE MHW= 10-20 FT

INSPECTION DATE : 06/30/87 INSPECTION TIME: 1505

- LAND CLASSIFICATION -

PERMIT NUMBER: 0

OWNER'S NAME : SOCIETY OF ST. EDMUND

ACCESS : PRIVATE

LAND USE : INSTITUTIONAL

- PHOTOS -

#1 ROLL 4 NEG 14-15 PANO. VIEW OF WALL LOOKING E. FR. MASON PT.
#2
#3
#4
#5

COMMENTS

AREA - SEE #60

NY 61.00 #1



INVENTORY NUMBER: 62.00

QUAD : MYSTIC
ADDRESS: ENDERS IS
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD
MAIN FUNCTION : TO PREVENT EROSION OF SHORELINE
MATERIAL : STONE

DESCRIPTION

APROX. L= 180 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1350

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE :

- PHOTOS -

#1 ROLL 6 NEG 16 REVETMENT FROM CENTER LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

ENTIRE SHORELINE OF ISLAND LINED WITH WALLS AND REVETMENTS

MY 62.00 #1



INVENTORY NUMBER: 63.00

QUAD : MYSTIC
ADDRESS: ENDERS ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: PIER CONDITION: GOOD
MAIN FUNCTION : RECREATIONAL, TRAPS SAND ON SOUTH SIDE
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX. L= 90 FT, W= 15 FT, H= 6 FT ABOVE MHW

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1410

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SOCIETY OF ST. EDMUND
ACCESS : PRIVATE
LAND USE : INSTITUTIONAL

- PHOTOS -

#1 ROLL 6 NEG 17 DOCK FROM STRUCTURE #62 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

MY 63.00 #1



INVENTORY NUMBER: 64.00

QUAD : MYSTIC
ADDRESS: ENDERS ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : TO PREVENT EROSION
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L= 180 FT, W= 2.5 FT, HEIGHT ABOVE MHW= 5 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1415

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : SOCIETY OF ST EDMUND
ACCESS : PRIVATE
LAND USE : TO PREVENT EROSION

- PHOTOS -

#1 ROLL 6 NEG 18 SEAWALL FROM BRIDGE
#2 ROLL 6 NEG 19 LOOKING NORTHWEST FROM ENDERS IS
#3
#4
#5

COMMENTS

MY 64.00 #1



MY 64.00 #2



INVENTORY NUMBER: 65.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF SLOPE FROM EROSION
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L= 300 FT, HEIGHT ABOVE MHW= 10 FT

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1445

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 21 LOOKING NORTH FROM SEAL ROCK TOWARDS BULKHEAD
#2 ROLL 6 NEG 20 MASON POINT FROM ENDERS ISLAND
#3
#4
#5

COMMENTS

ROCKY SHORE

MY 65.00 #2



MY 65.00 #1



INVENTORY NUMBER: 66.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS YARD IN FRONT OF HOME
MATERIAL : STONE&CONCRETE

DESCRIPTION

APROX. L=60 FT, W=1 FT, 3 FT ABOVE MHW

INSPECTION DATE : 07/07/87 INSPECTION TIME: 1455

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : VAN WINKLE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 6 NEG 22 MASON POINT FROM SEAL ROCK
#2 ROLL 6 NEG 23 BULKHEAD FROM WATER LOOKING EAST
#3 ROLL 6 NEG 24 RAM POINT FROM SEAL ROCKS
#4
#5


COMMENTS

NO EROSION PROTECTION NECESSARY

MY 65.00 #1



MY 66.00 #2



MY 66.00 #3



INVENTORY NUMBER: 67.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF SLOPE
MATERIAL : STONE

DESCRIPTION

APROX. HEIGHT 10 FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1032

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : MYSTIC RIVER MARINA
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 6 NEG 25, 26
#2 ROLL 7 NEG 1 *NOT USED*
#3 ROLL 7 NEG 2 REVETMENT AT MARINA LOOKING NORTH
#4 ROLL 7 NEG 3 FROM MARINA LOOKING NORTH
#5


COMMENTS

AREA OF MARINA - SEVERAL DOCKS FOR MOORING

MY 67.00 #1



MY 67.00 #3



MY 67.00 #4



INVENTORY NUMBER: 68.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: WALL/REVETMENT CONDITION: GOOD
MAIN FUNCTION : PROTECT PROPERTY AND STABILIZE SLOPE
MATERIAL : UNKNOWN

DESCRIPTION

APROX L=35 FT, HEIGHT =4FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1055

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 7 NEG 4 LOOKING SOUTHWEST FROM MARINA
#2
#3
#4
#5

COMMENTS

SHORELINE SALT MARSH VEGETATION AND OCCASIONAL ROCK

MY 68.00 #1



INVENTORY NUMBER: 69.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: FAIR
MAIN FUNCTION : PROTECTION AND RECREATION
MATERIAL : LOOSE STONE

DESCRIPTION

APROX. L= 60FT., 3FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1101

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVTE
ACCESS : PRIVATE
LAND USE : RECREATION

- PHOTOS -

#1 ROLL 7 NEG 5 LOOKING NORTH FROM MARINA
#2
#3
#4
#5

COMMENTS

MARSHY SHORE LINE

MY 69.00 #1



INVENTORY NUMBER: 70.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: FAIR
MAIN FUNCTION : PROTECTION AND SUPPORT OF LAND
MATERIAL : STONE&CEMENT

DESCRIPTION

APROX. L=120 FT, HEIGHT=4 FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1110

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 7 NEG 6 NORTH PORTION OF BULKHEAD
#2 ROLL 7 NEG 7 SOUTH PORTION OF BULKHEAD
#3
#4
#5


COMMENTS

SHORELINE ROCKY WITH PATCHES OF MARSH

MY 70.00 #1



MY 70.00 #2



INVENTORY NUMBER: 71.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : PROTECTION OF MOBILE HOME PARK
MATERIAL : CINDER BLOCKS

DESCRIPTION

SEAWALL IN FRONT OF MOBILE HOME PARK

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1139

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 7 NEG 8
#2
#3
#4
#5

COMMENTS

BROWERS COVE MARINA - NO EROSION CONTROL - DOCKS FOR
RECREATION. ADJACENT TO MARINA IS TRAILER PARK ON SMALL
PENNINSULA.

MY 71.00 #1



INVENTORY NUMBER: 72.00

QUAD : MYSTIC
ADDRESS: MASON ISLAND RD
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: CAUSEWAY TO IS. CONDITION: FAIR
MAIN FUNCTION : PROTECTION OF ROAD
MATERIAL : STONE

DESCRIPTION

APROX L=600 FT

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME :
ACCESS : PUBLIC
LAND USE :

- PHOTOS -

#1 ROLL 7 NEG 9 CAUSEWAY
#2
#3
#4
#5

COMMENTS

CAUSEWAY CONNECTS ISLAND TO MAINLAND.

MY 72.00 #1



INVENTORY NUMBER: 73.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : RETAINS LAND UNDER PARKING LOT. PREVENTS WAVE ERO
MATERIAL : WOOD

DESCRIPTION

APROX 4 FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1344

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 7 NEG 10 RAILROAD BRIDGE FROM MYSTIC COVE BOAT SALES
#2 ROLL 7 NEG 11 BULKHEAD LOOKING WEST
#3
#4
#5

COMMENTS

MARINA AND BOAT SALES

MY 73.00 #1



MY 73.00 #2



INVENTORY NUMBER: 74.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PREVENT EROSION FROM YARDS
MATERIAL : CONCRETE

DESCRIPTION

APROX 3FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1348

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 7 NEG 12 SEAWALL LOOKING WEST
#2
#3
#4
#5

COMMENTS

SHORE IS MUD FLATS WITH SALT MARSH

MY 71.22 #1



INVENTORY NUMBER: 75.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PROTECTION AND RETENTION
MATERIAL : CEMENT & STONE

DESCRIPTION

HEIGHT 3 FT ABOVE MHW
CEMENT SEAWALL WITH STONE RIPRAP

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1353

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 7 NEG 13 WALL LOOKING WEST
#2
#3
#4
#5

COMMENTS

MY 75.00 51



INVENTORY NUMBER: 76.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : RETAINS PROPERTY, PREVENT EROSION
MATERIAL : STONE

DESCRIPTION

HEIGHT 3 TO 4 FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1400

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 7 NEG 14 WALL LOOKING WEST
#2
#3
#4
#5

COMMENTS

HOMEOWNERS WORKING ON SEAWALL TO REPAIR IT

NY 76.00 #1



INVENTORY NUMBER: 77.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : RETENTION AND PROTECTION
MATERIAL : CEMENTED ROCKS

DESCRIPTION

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1405

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 7 NEG 15 WALL LOOKING WEST
#2
#3
#4
#5

COMMENTS

MY 77.00 #1



INVENTORY NUMBER: 78.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD
MAIN FUNCTION : RETENTION
MATERIAL : WOOD

CONDITION: POOR

DESCRIPTION

HEIGHT 3 TO 4 FT ABOVE MHW

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1423

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 7 NEG 16 LOOKING EAST
#2
#3
#4
#5

COMMENTS

PENNINSULA HEADING OUT TO MURPHY POINT. MARSHY LOW AREA.
HEADING OUT TO BREWER'S YACHT YARD.

MY 73.00 #1



INVENTORY NUMBER: 79.00

QUAD : MYSTIC
ADDRESS: MURPHY POINT
TOWN : STONINGTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD-POOR
MAIN FUNCTION : RETENTION
MATERIAL : WOOD

DESCRIPTION

APROX L= 1000 FT

INSPECTION DATE : 07/08/87 INSPECTION TIME: 1434

- LAND CLASSIFICATION -


PERMIT NUMBER: 850038
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 7 NEG 17,18 PICTURE OF BULKHEAD
#2 ROLL 7 NEG 19-22 PICTURE LOOKING EAST FROM YACHTLAND AROUND
#3 TO TRAIN TRESTLE. DID NOT INVENTORY STRUCTURE SERIES OF
#4 BULKHEADS AND SEAWALL.
#5

COMMENTS

BREWER'S YACHT YARD





INVENTORY NUMBER: 80.00

QUAD : MYSTIC
ADDRESS: CARSON ROAD, MYSTIC HARBOR
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : SLOPE EROSION PROTECTION
MATERIAL : ROCK

DESCRIPTION

HEIGHT 4 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1150

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 1 STRUCTURE LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

SITE ADJACENT TO RAILROAD BRIDGE



INVENTORY NUMBER: 81.00

QUAD : MYSTIC
ADDRESS: CARSON ROAD, MYSTIC HARBOR
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: POOR
MAIN FUNCTION : SLOPE EROSION PROTECTION
MATERIAL : ROCK

DESCRIPTION

HEIGHT = 2-3 FT ABOVE MHW. VARIATION DUE TO DISREPAIR

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : NOANK VILLAGE BOATYARD
ACCESS : NOANK VILLAGE BOATYARD
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 8 NEG 3 STRUCTURE IN FOREGROUND LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

ADJACENT TO BENCHMARK, 700 YARDS FROM RAILROAD DIKE.

MY 31.00 #1



INVENTORY NUMBER: 82.00

QUAD : MYSTIC
ADDRESS: CARSON ROAD, MYSTIC HARBOR --
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: POOR
MAIN FUNCTION : SHORE STABILIZATION
MATERIAL : WOOD AND ROCK

DESCRIPTION

APROX L= 65 FT, HEIGHT 3FT ABOVE MHW. WOOD BULKHEAD WITH
ROCK FILL BEHIND.

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1202

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 4 STRUCTURE FROM PIER TO NORTH LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

MY 32.00 #1



INVENTORY NUMBER: 83.00

QUAD : MYSTIC
ADDRESS: MYSTIC HARBOR
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : SLOPE STABILIZATION AND EROSION PROTECTION
MATERIAL : STONES&CEMENT

DESCRIPTION

APROX L= 100 FT, HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1205

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 5 STRUCTURE LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

WILLOW POINT MARINA DOCK ADJACENT #82 NO PERMIT (H. WITZZ)
ARLENE BULCER DOCK ON OTHER SIDE - NO PERMIT FOR DOCK
EXTENSION.



INVENTORY NUMBER: 84.00

QUAD : MYSTIC
ADDRESS: WILLOW POINT
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD
MAIN FUNCTION : SLOPE STABILIZATION
MATERIAL : ROCK

CONDITION: FAIR

DESCRIPTION

HEIGHT= 3-4 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1220

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL


- PHOTOS -

#1 ROLL 8 NEG 7,8 ROCK BULKHEAD WITH DOCKING FACILITIES FROM IT
#2
#3
#4
#5

COMMENTS

MARINA MYSTIC SHIPYARD WILLOW POINT - SIZABLE MARINA

NY 3-1-03 #1



INVENTORY NUMBER: 85.00

QUAD : MYSTIC
ADDRESS: WILLOW POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT&WALL CONDITION: FAIR
MAIN FUNCTION : SLOPE STABILIZATION AND EROSION PREVENTION
MATERIAL : STONE&CONCRETE

DESCRIPTION

REVETMENT L= 200FT (ROCKS ONLY)
SEAWALL L= 30 FT (CONCRETE)

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 8 NEG 9 STRUCTURE LOOKING SOUTHWEST
#2 ROLL 8 NEG 10-12 PANORAMIC VIEW FROM PIER AT CENTER OF
#3 STRUCTURE.
#4
#5

COMMENTS

MYSTIC YACHT CENTER

MY 25.00 #1



MY 25.00 #2



INVENTORY NUMBER: 86.00

QUAD : MYSTIC
ADDRESS: WILLOW POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SLOPE STABILIZATION AND EROSION PREVENTION
MATERIAL : STONE&CEMENT

DESCRIPTION

APROX L= 100 FT, HEIGHT = 2FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1225

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 13, 14 STRUCTURE LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

SOME SCOURING IN BACK OF STRUCTURE

MY 36.00 #1



INVENTORY NUMBER: 87.00

QUAD : MYSTIC
ADDRESS: ESSEX ST., SPENCE POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SLOPE STABILIZATION, RETENTION, EROSION PREVENTION
MATERIAL : STONE&CEMENT

DESCRIPTION

APROX L= 100 FT HEIGHT= 2 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1240

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 15 STRUCTURE LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

SOME BACKSIDE SCOUR

MY 37.00 #1



INVENTORY NUMBER: 88.00

QUAD : MYSTIC
ADDRESS: ESSEX ST., SPENCE POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SLOPE STABILIZATION, PREVENT EROSION, PROTECT SHOR
MATERIAL : STONE&CEMENT

DESCRIPTION

APROX L= 100 FT, HEIGHT 2FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1415

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 16 STRUCTURE LOOKING SOUTHWEST FROM PEIR NORTH OF
#2 STRUCTURE.
#3
#4
#5

COMMENTS

NOTED BACK SCOUR OCCURS AT WALLS ON SPENCE POINT

MY 38.00 #1



INVENTORY NUMBER: 89.00

QUAD : MYSTIC
ADDRESS: ESSEX ST., SPENCE POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : EROSION PROTECTION AND SHORE STABILIZATION
MATERIAL : STONE&CEMENT

DESCRIPTION

APROX L= 300 FT HEIGHT 3 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1420

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 8 NEG 17 EAST HALF OF SEAWALL LOOKING SOUTH
#2 ROLL 8 NEG 18 WEST HALF OF SEAWALL LOOKING SOUTH
#3
#4
#5

COMMENTS

SEAWALL EXTENDS AROUND PERIMETER OF PROPERTY (SPENCER POINT)
RIPRAP AT SOME PLACES

MY 39.00 #1



MY 39.00 #2



INVENTORY NUMBER: 90.00

QUAD : MYSTIC
ADDRESS: COVE LANE, SPENCE POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : SHORE EROSION PROTECTION
MATERIAL : STONE

DESCRIPTION

APROX L= 100 FT, HEIGHT 1-2 FT ABOVE MHW

INSPECTION DATE : 07/14/87 INSPECTION TIME: 1425

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 19 RIPRAP LOOKING NORTH
#2
#3
#4
#5

COMMENTS

THIS CONCLUDES SPENCE POINT - THE REST OF THE AREA IS MARSH
WITH RAILROAD DIKE RUNNING PARALLEL TO SHORE. SIX PENNY
ISLAND SIGHTED FROM SHORE - NO STRUCTURE SEEN.

MY 90.00 #1



INVENTORY NUMBER: 91.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD
MAIN FUNCTION : SLOPE STABILIZATION AND EROSION PREVENTION
MATERIAL : STONE

DESCRIPTION

HEIGHT 4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1035

- LAND CLASSIFICATION -

PERMIT NUMBER: 840135
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 8 NEG 20 FROM BOATYARD LOOKING NORTH UP R.R. DIKE
#2 ROLL 8 NEG 21 RIPRAP SLOPE
#3 ROLL 8 NEG 22 CEMENTED RIPRAP BULKHEAD ADJ. TO BOAT LAUNCH
#4
#5

COMMENTS

AT NOANK VILLAGE BOAD YARD
REVTMENT COMPOSED OF RIPRAP SLOPE

MY 91.00 #1



MY 91.00 #2



MY 91.00 #3



INVENTORY NUMBER: 92.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD
MAIN FUNCTION : SLOPE STABILIZATION
MATERIAL : STONE

DESCRIPTION

APROX L= 450 FT, HEIGHT= 3 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1045

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 23 STRUCTURE LOOKING SOUTH FROM PIER TO NORTH
#2
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 93.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL&DOCK CONDITION: GOOD
MAIN FUNCTION : SHORE PROTECTION
MATERIAL : CEMENTED ROCK

DESCRIPTION

HEIGHT= 5 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1055

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 8 NEG 24 SEAWALL FROM NOANK VILLAGE BOAT YARD-NOTE PIER
#2 ROLL 8 NEG 25 OLD DOCK FOUNDATION
#3 ROLL 8 NEG 26 SEAWALL
#4 ROLL 8 NEG 27 LOOKING SOUTH
#5

COMMENTS

MY 93.00 #1



MY 93.00 #2



MY 93.00 #3



MY 93.00 #4



INVENTORY NUMBER: 94.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SHORE STABILIZATION AND EROSION PREVENTION
MATERIAL : CONCRETE

DESCRIPTION

APROX L= 51 FT, W= 8 FT W/ 2FT ROCK FACADE, H= 3 FT ABOVE
MHW.

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1115

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 2 TOP DECKING OF STRUCTURE
#2
#3
#4
#5

COMMENTS

ROLL 9 NEG 1 BULKHEAD FROM SHORE DID NOT DEVELOP

MY 94.00 #1



INVENTORY NUMBER: 95.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: FAIR
MAIN FUNCTION : MAINTAIN SHORE FRONT AND PREVENT EROSION
MATERIAL : LARGE BOULDERS

DESCRIPTION

APROX TOTAL L= 250 FT, HEIGHT= 3-5 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1125

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : RAM ISLAND YACHT CLUB
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -


#1 ROLL 9 NEG 3 DESCRIBED STRUCTURE
#2 ROLL 9 NEG 4,5 SCOUR ON BACKSIDE OF REVETMENT
#3
#4
#5

COMMENTS

MY 95.00 #2



MY 95.00 #2



INVENTORY NUMBER: 96.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : SLOPE PROTECTION
MATERIAL : LARGE BOULDERS

DESCRIPTION

APROX L= 240 FT. HEIGHT= 8 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1130

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 9 NEG 6 BULKHEAD AND SEAWALL FRONT
#2 ROLL 9 NEG 7,8 HOUSE AND BOATHOUSE WITH WARE ATTENUATOR
#3 ROLL 9 NEG 9 SOUTHSIDE OF PROPERTY
#4
#5


COMMENTS

WAS DOCK FOR TOWN BEFORE
DEVELOPED BY PRIVATE OWNER.

MY 96.00 #1



MY 96.00 #2



MY 96.00 #3



INVENTORY NUMBER: 97.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD/FAIR
MAIN FUNCTION : RETAIN LAND AND PREVENT EROSION
MATERIAL : ROCK

DESCRIPTION

HEIGHT= 3 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1150

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 10 STRUCTURE FROM SITE 96
#2 ROLL 9 NEG 11 SOUTH HALF OF WALL LOOKING SOUTH FROM BEACH IN
#3 FRONT OF SEAWALL.
#4
#5

COMMENTS

MY 97.00 #1



MY 97.00 #2



INVENTORY NUMBER: 98.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVELTMENT CONDITION: GOOD
MAIN FUNCTION : PREVENT AND HALT EROSION
MATERIAL : ROCK

DESCRIPTION

HEIGHT= 3-4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1200

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 12 REVELTMENT LOOKING EAST FROM OWNER'S BACK YARD
#2
#3
#4
#5

COMMENTS

MY 92.00 #1



INVENTORY NUMBER: 99.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : STABILIZE SLOPE AND PREVENT EROSION
MATERIAL : STONE

DESCRIPTION

HEIGHT= 3-5 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1205

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 13,14 PANORAMIC VIEW OF REVETMENT LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

FOUNDATION FOR HOME ON BEDROCK. DOCK EXTENDS FROM REVETMENT

MY 09.00 #1



INVENTORY NUMBER: 100.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : SLOPE PROTECTION AND EROSION PREVENTION
MATERIAL : STONE

DESCRIPTION

HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1210

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 15-18 PANORAMIC VIEW OF STRUCTURE 100 AND 101
#2
#3
#4
#5

COMMENTS

MY 100.00 #1



INVENTORY NUMBER: 101.00

QUAD : MYSTIC
ADDRESS: 8 FRONT ST., NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PROTECT SHORE AND PREVENT EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX TOTAL L= 365 FT, HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1220

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : L. CHRISTY
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 9 NEG 17,18 SEE STRUCTURE 100
#2
#3
#4
#5

COMMENTS

ADJACENT TO TOWN DOCK

MY 101.00 #1



INVENTORY NUMBER: 102.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : PROVIDE RECREATION AREA AND PREVENT EROSION
MATERIAL : STONE

DESCRIPTION

HEIGHT= 3 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1225

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : TOWN DOCK
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 9 NEG 19 SEAWALL AND TOWN BEACK LOOKING NORTHEAST
#2
#3
#4
#5

COMMENTS

MY 102.00 #1



INVENTORY NUMBER: 103.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP
MAIN FUNCTION : MARINE RESEARCH LAB
MATERIAL : STONE

CONDITION: FAIR

DESCRIPTION

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1230

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : UNIVERSITY OF CONNECTICUT
ACCESS : STATE OWNED
LAND USE : INSTITUTIONAL

- PHOTOS -

#1 ROLL 9 NEG 20 RIPRAP LOOKING NORTH
#2 ROLL 9 NEG 21-23 PANORAMIC OF AREA LOOKING SOUTH
#3 ROLL 9 NEG 24 SOUTH END OF STRUCTURE LOOKING NORTH
#4
#5

COMMENTS

RIPRAP HAS SOME SCOUR AND SOME CAP ROCKS HAVE BEEN MOVED

MY 103.00 #1



MY 103.00 #2



MY 103.00 #3



INVENTORY NUMBER: 104.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: GOOD
MAIN FUNCTION : STABILIZE SLOPE AND PREVENT EROSION
MATERIAL : STONE ON CEMENT

DESCRIPTION

APROX L= 100 FT, HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1415

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 9 NEG 25 STRUCTURE FROM 105 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

MY 104.00 #1



INVENTORY NUMBER: 105.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : STABILIZE SLOPE AND PREVENT EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1430

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 9 NEG 26 STRUCTURE FROM 104 LOOKING SOUTH
#2 ROLL 10 NEG 1 DID NOT DEVELOP (STRUCTURE FROM PIER)
#3 ROLL 10 NEG 2 STRUCTURE FROM PIER EXTENDING FROM CENTER
#4 LOOKING SOUTHWEST
#5

COMMENTS

RIPRAP PLACED UP TO MHW LEVEL AT ONE END OF STRUCTURE

MY 105.00 #1



MY 105.00 #3



INVENTORY NUMBER: 106.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : DOCKING AND EROSION PROTECTION
MATERIAL : LARGE BOULDERS

DESCRIPTION

APROX L= 80 FT, HEIGHT= 2-4 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1440

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 10 NEG 3 STRUCTURE LOOKING SOUTH FROM PIER
#2
#3
#4
#5

COMMENTS

SOME SCOUR WITH REPAIRS DONE. PROTECTS PARKING LOT.

NY 10-100 #1



INVENTORY NUMBER: 107.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR-POOR
MAIN FUNCTION : BANK STABILIZATION AND EROSION PREVENTION
MATERIAL : STONE

DESCRIPTION

HEIGHT 1-5 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1450

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : 5 LOTS-PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL/RECREATIONAL

- PHOTOS -

#1 ROLL 10 NEG 4-7 SHOTS OF RIPRAP IN VARIOUS SPOTS LOOKING
#2 SOUTH AND/OR SOUTHWEST
#3
#4
#5

COMMENTS

SOME SCOUR. AREA 107 IS FROM PARKING LOT (106). SOUTH TO
REVETMENT NEAR MARINA.



INVENTORY NUMBER: 108.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : UNKNOWN - MAY HAVE BEEN DOCK FOUNDATION
MATERIAL : ROCK

DESCRIPTION

APROX L= 30 FT, W= 4 FT, HEIGHT 0-2 FT BELOW MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1500

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 10 NEG 8 STRUCTURE LOOKING EAST FROM BASE
#2
#3
#4
#5

COMMENTS

STRUCTURE SUBMERGED. MAY HAVE BEEN DOCK.

MY 103.00 #1



INVENTORY NUMBER: 109.00

QUAD : MYSTIC
ADDRESS: NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: FAIR
MAIN FUNCTION : PREVENT EROSION
MATERIAL : STONE

DESCRIPTION

APROX L= 150 FT, HEIGHT= 5 FT ABOVE MHW

INSPECTION DATE : 07/15/87 INSPECTION TIME: 1515

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : ABBOTS LOBSTER INTHE RUFF
ACCESS : PUBLIC
LAND USE : COMMERCIAL

- PHOTOS -

#1 ROLL 10 NEG 9 NORTH SIDE WITH SOME SCOUR
#2 ROLL 10 NEG 10 WATERFRONT AREA OF RIPRAP
#3
#4
#5

COMMENTS

OWNER ADDRESS 117 PEARL ST.

MY 109.00 #1



MY 109.00 #2



INVENTORY NUMBER: 110.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BULKHEAD CONDITION: FAIR
MAIN FUNCTION : RETAINS PARKING AREA
MATERIAL : CEMENT/STL PILE

DESCRIPTION

HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1215

- LAND CLASSIFICATION -

PERMIT NUMBER: 800089
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : COMMERCIAL


- PHOTOS -

#1 ROLL 10 NEG 11 NOANK SHIPYARD LOOKING TOWARDS ABBOTTS
#2 ROLL 10 NEG 12 NOANK SHIPYARD BULKHEAD
#3
#4
#5

COMMENTS

PERMIT IS FOR PIER AND FILL NOT FOR BULKHEAD
PAVEMENT FALLING IN AT SEVERAL PLACES

MY 110.00 #2



MY 110.00 #2



INVENTORY NUMBER: 111.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : PREVENT EROSION AND STABILIZE SLOPE
MATERIAL : STONE

DESCRIPTION

APROX L= 100 FT, HEIGHT= 5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1220

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 10 NEG 13 STRUCTURE FROM NOANK BOAT YARD
#2
#3
#4
#5

COMMENTS

MY 111.00 #1



INVENTORY NUMBER: 112.00

QUAD : MYSTIC --
ADDRESS: PEARL ST., MORGAN POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SUPPORT LAND AND PREVENT EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 120 FT, HEIGHT= 4-5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1235

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -


#1 ROLL 10 NEG 14 NORTH HALF OF STRUCTURE LOOKING NORTH FROM
#2 OTHER HALF
#3 ROLL 10 NEG 15 SOUTH HALF OF STRUCTURE FROM CORNER BETWEEN
#4 NORTH AND SOUTH HALVES
#5

COMMENTS

MY 112.00 #1



MY 112.00 #2



INVENTORY NUMBER: 113.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, MORGAN PT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : RETAIN YARD IN FRONT OF HOME
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 330, HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1245

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 10 NEG 16 EAST HALF OF STRUCTURE LOOKING NORTH
#2 ROLL 10 NEG 17 WEST HALF OF STRUCTURE LOOKING WEST
#3
#4
#5


COMMENTS

BEDROCK EXPOSURE AT POINT IN FRONT OF SEAWALL

MY 113.00 #1



MY 113.00 #2



INVENTORY NUMBER: 114.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, MORGAN PT -
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SUPPORT AND PROTECT LAND, PREVENT EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 400 FT, HEIGHT= 3.5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1250

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 10 NEG 18 EAST HALF OF STRUCTURE LOOKING EAST
#2 ROLL 10 NEG 19 WEST HALF OF STRUCTURE LOOKING WEST
#3
#4
#5

COMMENTS

LOOSE BOULDERS PLACED ON TOP IN SOME PLACES (100 FT)

MY 114.00 #1



MY 114.00 #2



INVENTORY NUMBER: 115.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, MORGAN PT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: PIER CONDITION: POOR
MAIN FUNCTION : UNKNOWN - POSSIBLY WAS A MOORING
MATERIAL : CONCRETE

DESCRIPTION

APROX L= 150 FT, HEIGHT= 0 TO 3.5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1255

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 10 NEG 20 STRUCTURE LOOKING SOUTHWEST FROM BASE
#2
#3
#4
#5

COMMENTS

HAZARD TO NAVIGATION. BEDROCK SHORE - WATER UP TO SEAWALL
AROUND POINT - NO SHORE AREA TO SPEAK OF. OWNER NOTED WOULD
BE REPLACING PIER.

MY 115.00 #1



INVENTORY NUMBER: 116.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, WEST COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF SHORE FROM EROSION
MATERIAL : ROCK

DESCRIPTION

APROX L= 500 FT, HEIGHT= 8 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1310

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 10 NEG 21 STRUCTURE LOOKING NORTH
#2
#3
#4
#5

COMMENTS

MY 115.00 #1



INVENTORY NUMBER: 117.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, WEST COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : PREVENT EROSION, STABILIZE SHORE, PROVIDE MOORING
MATERIAL : STONE

DESCRIPTION

APROX L= 220 FT, HEIGHT= 4-7 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1320

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 10 NEG 22-24 PANORAMIC VIEW OF STRUCTURE LOOKING NORTH
#2 AND WEST FROM EASTERN CORNER
#3
#4
#5

COMMENTS



INVENTORY NUMBER: 118.00

QUAD : MYSTIC
ADDRESS: PEARL ST., NOANK, WEST COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : PROTECT SHORE, PREVENT EROSION
MATERIAL : STONE

DESCRIPTION

HEIGHT= 10 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1330

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 10 NEG 25 LOOKING SOUTH
#2 ROLL 10 NEG 26 LOOKING NORTH
#3
#4
#5

COMMENTS

MY 113.00 #1



MY 113.00 #2



INVENTORY NUMBER: 119.00

QUAD : MYSTIC
ADDRESS: 37-41 SPRING ST., NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SUPPORT LAND AND PREVENT EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 120 FT, HEIGHT= 5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1335

- LAND CLASSIFICATION -

PERMIT NUMBER: 780053
OWNER'S NAME : WHITTAKER BOAT YARD
ACCESS : PRIVATE AT FOOT OF ST
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 1 NEG 1 PICTURE DID NOT COME OUT - LOOKING NORTH
#2
#3
#4
#5

COMMENTS

NO PHOTOGRAPHS

INVENTORY NUMBER: 120.00

QUAD : MYSTIC
ADDRESS: WEST COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL & DOCK CONDITION: FAIR
MAIN FUNCTION : SUPPORT LAND AND PROTECT FROM EROSION
MATERIAL : CINDR BLK/BOLDR

DESCRIPTION

APROX L= 180 FT, HEIGHT= 4-5 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1350

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 1 NEG 2 LOOKING SOUTH
#2
#3
#4
#5

COMMENTS

BOULDERS IN FRONT OF SEAWALL

NY 123.00 #1



INVENTORY NUMBER: 121.00

QUAD : MYSTIC
ADDRESS: WEST COVE
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SUPPORT OF LAND AND EROSION PROTECTION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 300 FT, HEIGHT= 4 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1355

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE-OFF OF COVE ST.
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11 NEG 3
#2
#3
#4
#5

COMMENTS

MY 111.00 #1



INVENTORY NUMBER: 122.00

QUAD : MYSTIC
ADDRESS: WEST COVE
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : SUPPORT OF LAND AND EROSION CONTROL
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 20 FT, HEIGHT= 3 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1410

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11 NEG 5 NORTH FACE OF SEAWALL LOOKING EAST
#2 ROLL 11 NEG 4 NORTH FACE OF SEAWALL LOOKING SOUTH
#3
#4
#5

COMMENTS

SPICES MARINA-COMPLAIN FROM NEIGHBOR-BLOCKING COVE AREA.
TOO MANY MOORINGS FOR COVE. MANY PUBLIC MEETINGS OVER
MARINA AREA.

MY 122.00 #1



MY 122.00 #2



INVENTORY NUMBER: 123.00

QUAD : MYSTIC
ADDRESS: WEST COVE
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS
MAIN FUNCTION : PREVENT EROSION
MATERIAL : STONES

CONDITION: FAIR

DESCRIPTION

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1510

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : SPICES MARINA
ACCESS : PRIVATE
LAND USE : RECREATIONAL


- PHOTOS -

#1 ROLL 11 NEG 6-9 MARINA FROM OTHER SIDE OF COVE
#2 ROLL 11 NEG 10-13 SEAWALLS AT MARINA AND ASSOC. STRUCTURES.
#3
#4
#5

COMMENTS

MARINA HAS TAKEN OVER WEST BANK OF WEST COVE. SEAWALLS USED
FOR MOORING.

NY 120.00 #1



INVENTORY NUMBER: 123.00

SEE PAGE B261

NY 123.00 #2



INVENTORY NUMBER: 124.00

QUAD : MYSTIC
ADDRESS: MARSH ROAD, WEST COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION:
MAIN FUNCTION : PROTECTION OF MOORING AREA
MATERIAL : TIMBER & STONE

DESCRIPTION

APROX L= 760 FT, W= 19 FT

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1525

- LAND CLASSIFICATION -

PERMIT NUMBER: 840108
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 10 NEG 27 BREAKWATER FROM SITE 117 ON EAST SIDE OF COVE
#2 ROLL 11 NEG 14 BREAKWATER FROM WEST SHORE OF WEST COVE
#3 ROLL 15 NEG 1,2 BREAKWATER FROM STRUCTURE 125
#4
#5

COMMENTS


MY 124.00 #1



MY 124.00 #2



MY 124.00 #3



INVENTORY NUMBER: 125.00

QUAD : MYSTIC
ADDRESS: WEST COVE
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : BANK STABILIZATION
MATERIAL : CEMENTED ROCK

DESCRIPTION

APROX L= 400 FT, HEIGHT= 4-6 FT ABOVE MHW

INSPECTION DATE : 07/16/87 INSPECTION TIME: 1530

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11 NEG 15 SPICERS BREAKWATER INCLUDED WITH SEAWALL
#2
#3
#4
#5

COMMENTS

NATURAL BEDROCK EXPOSED. SEAWALL PROTECTS GRASS YARD AND
HOUSE FROM SALTWATER. LOCATED SOUTH OF SPICERS MARINA.

MY 125.00 #1



INVENTORY NUMBER: 126.00

QUAD : MYSTIC
ADDRESS: EKSER COVE, NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SHORE STABILIZATION AND PROTECTION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 200 FT, W= 1.5 FT, HEIGHT= 5 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1400

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL


- PHOTOS -

#1 ROLL 11A NEG 14 SEAWALL FROM WEST SIDE
#2 ROLL 15 NEG 3 SEAWALL FROM WEST SIDE
#3
#4
#5


COMMENTS

EXPOSED BEDROCK AT POINT BETWEEN STRUCTURES 125 AND 126

MY 125.00 #1



MY 126.00 #2



INVENTORY NUMBER: 127.00

QUAD : MYSTIC
ADDRESS: ESKER COVE, NOANK
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR
MAIN FUNCTION : SUPPORT OF LAND AND EROSION PROTECTION
MATERIAL : STONE IN CEMENT

DESCRIPTION

APROX L= 100 FT, W= 1.5 FT, H= 4 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1400

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11A NEG 15 SEAWALL FROM EAST
#2 ROLL 11A NEG 16 DAMAGED AREA FROM EAST
#3 ROLL 15 NEG 4 SEAWALL FROM EAST
#4 ROLL 15 NEG 6 DAMAGED AREA FROM WEST
#5

COMMENTS

DAMAGE PROBABLY CAUSED BY SCOUR AND EROSION. OWNER SAYS A
CATAMARAN HIT DAMAGED AREA DURING HURRICANE GLORIA.

MY 127.00 #1



MY 127.00 #2



MY 127.00 #3



MY 127.00 #4



INVENTORY NUMBER: 128.00

QUAD : MYSTIC
ADDRESS: NOANK, ESKER COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: POOR-FAIR
MAIN FUNCTION : SUPPORT OF LAND AND EROSION PREVENTION
MATERIAL : CEMENT

DESCRIPTION

APROX L= 100 FT, W= 8 FT, H= 4 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1415

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11 NEG 20,21 SEAWALL
#2 ROLL 15 NEG 7 WEST END OF STRUCTURE LOOKING NORTH FROM PIER
#3 ROLL 15 NEG 8 EAST END OF STRUCTURE LOOKING NORTH FROM PIER
#4
#5

COMMENTS

BOAT RAMP ON WEST END OF STRUCTURE. PUBLIC RIGHT OF WAY TO
BOAT RAMP.

MY 128.00 #1



MY 128.00 #2



MY 128.00 #3



INVENTORY NUMBER: 129.00

QUAD : MYSTIC
ADDRESS: NOANK, ESKER COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALLS&DOCKS CONDITION: FAIR
MAIN FUNCTION : PREVENT EROSION
MATERIAL : STONE, CONCRETE

DESCRIPTION

APROX L= 250 FT, W= 4-8 FT (VARIES WITH OWNER), H= 4 FT ABOVE
MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1435

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 11A NEG 23-25 SEAWALL IN FRONT OF 5 HOMES
#2 ROLL 12 NEG 2,3
#3 ROLL 15 NEG 9 STRUCTURE FROM BOAT RAMP
#4 ROLL 15 NEG 10-12 STRUCTURE LOOKING WEST
#5


COMMENTS

OWNER NOTED PORTIONS OF SEAWALL HAVE BEEN REPLACED SINCE
HURRICANE GLORIA. 2 DOCKS OFF SEAWALL. PART OF SEAWALL IS
WOODEN.

MY 129.00 #1



MY 129.00 #2



INVENTORY NUMBER: 130.00

QUAD : MYSTIC
ADDRESS: NOANK, ESKER COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SUPPORT OF LAND AND SHORE PROTECTION
MATERIAL : CEMENT+WOODPILE

DESCRIPTION

SPROX L= 30 FT, W= 8 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1440

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -


#1 ROLL 11A NEG 25,26 SEAWALL WITH WOOD PILING AS FACADE WITH
#2 SMALL DOCK OFF FROM
#3 ROLL 12 NEG 1 WOOD PILING
#4 ROLL 15 NEG 13,14 PANORAMIC OF SEAWALL LOOKING NORTH
#5

COMMENTS

MY 130.00 #1



MY 130.00 #3



INVENTORY NUMBER: 131.00

QUAD : MYSTIC
ADDRESS: NOANK, ESKER COVE
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : BANK PROTECTION
MATERIAL : CEMENT AND WOOD

DESCRIPTION

APROX L= 60 FT, W= 4-8 FT. H= 5 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1500

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 12 NEG 4 SEAWALL STRUCTURE
#2
#3
#4
#5

COMMENTS

MY 131.00 #1



INVENTORY NUMBER: 132.00

QUAD : MYSTIC
ADDRESS: NOANK, ESKER COVE
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : EROSION PROTECTION OF LAND IN FRONT OF HOME
MATERIAL : CEMENT

DESCRIPTION

APROX L= 45 FT, W= 15 FT, H= 3 FT ABOVE MHW

INSPECTION DATE : 07/21/87 INSPECTION TIME: 1510


- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 12 NEG 5 SEAWALL
#2 ROLL 12 NEG 6,7 ESKER BEACH FROM STRUCTURE
#3
#4
#5

COMMENTS



MY 132.00 #2



INVENTORY NUMBER: 133.00

QUAD : MYSTIC
ADDRESS: ESKER POINT
TOWN : GROTON STATE : CT
COUNTY : NEW LONDON

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF SHORELINE
MATERIAL : STONE & ROCK

DESCRIPTION

APROX L= 500 FT, W= 10 FT (VARIES), HEIGHT= 6-8 FT ABOVE MHW

INSPECTION DATE : 07/22/87 INSPECTION TIME: 1130

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 12 NEG 8 RIPRAP
#2 ROLL 12 NEG 9 RIPRAP REVETMENT NORTHEAST SIDE OF ESKER POINT
#3 ROLL 12 NEG 10 RIPRAP REVETMENT LOOKING BACK TO ESKER BEACH
#4
#5

COMMENTS

ESKER BEACH-BEACH AREA WITH SWIMMING AND PICNIC TABLES AND
CONCESSION STAND (FOOD). PAID PARKING ACROSS STREET.

MY 133.00 #1



MY 133.00 #2



MY 133.00 #3



INVENTORY NUMBER: 134.00

QUAD : MYSTIC
ADDRESS: ESKER POINT
TOWN : GROTON
COUNTY : NEW LONDON

STATE : CT

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: RIPRAP & DOCK CONDITION: GOOD
MAIN FUNCTION : PROTECTION OF SLOPE
MATERIAL : STONE & ROCK

DESCRIPTION

APROX L= 500 FT, W= 10 FT (VARIES), H= 6-8 FT ABOVE MHW

INSPECTION DATE : 07/22/87 INSPECTION TIME: 1145

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 12 NEG 11 NORTHWEST SIDE OF ESKER POINT
#2
#3
#4
#5

COMMENTS

MARSHY SMALL BEACH AREA BETWEEN 133 AND 134. CONTINUATION
OF 133.

MR 174.35 #1

